RAY International Electrical Contracting & Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

TOOL BOX TALKS

Abu Dhabi/ Dubai

Project Name:
SangProject2(name)

Location:
Dlh

Client: No Client

Supervisor

Date: 24-08-2023

No.of manpower: 5

Time: 11:59

Job type: g

Job Description:
h

Tools and Equipment used:
h

Job Start: 11:54:00

End Time: 11:54:00

Conducted By:
sijina-test

Ray No. : RU/603

Signature:

Life Saving Rules: Tick on the boxes which you being discuss during TBT	
Don't walk under a suspended load	☑
Don't smoke outside designed smoking areas	☑
Conduct gas test when required	☐
Work with a valid work permit when required	☑
No drugs or alcohol while working or driving	☑
While driving don't use the mobile phone and exceed speed limit	☐
Obtain permit for working in confined Space	☑
Verify isolation before work begins and use the specified life protection	☑
Wear your seat belt	☑
Obtain authorization before overriding	☐
Follow prescribed journey	☑
Protect yourself against a fall when working at height	☑

Use hazards warning signs as remainders and tick the signs being discussed during TBT

☑	☑	☑	☑	☑	☑	☑	☑	☑

ATTENDANCE SHEET

S.No	Emp.No.	Name	Company	Designation	Signature
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115

Project Name:

SangProject2(name)

Location:

Dlh

Client: No Client

Supervisor

Date: 24-08-2023

No.of manpower: 5

Time: 11:59

Job type: g

Job Description:

h

Tools and Equipment used:

h

Job Start: 11:54:00

End Time: 11:54:00

Conducted By:

sijina-test

Ray No. : RU/603

Signature:

Life Saving Rules: Tick on the boxes which you being discuss during TBT	
Don't walk under a suspended load	☑
Don't smoke outside designed smoking areas	☑
Conduct gas test when required	☐
Work with a valid work permit when required	☑
No drugs or alcohol while working or driving	☑
While driving don't use the mobile phone and exceed speed limit	☐
Obtain permit for working in confined Space	☑
Verify isolation before work begins and use the specified life protection	☑
Wear your seat belt	☑
Obtain authorization before overriding	☐
Follow prescribed journey	☑
Protect yourself against a fall when working at height	☑

Use hazards warning signs as remainders and tick the signs being discussed during TBT

☑	☑	☑	☑	☑	☑	☑	☑	☑

ATTENDANCE SHEET

S.No	Emp.No.	Name	Company	Designation	Signature
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115

Project Name:

SangProject2(name)

Location:

Dlh

Client: No Client

Supervisor

Date: 24-08-2023

No.of manpower: 5

Time: 11:59

Job type: g

Job Description:

h

Tools and Equipment used:

h

Job Start: 11:54:00

End Time: 11:54:00

Conducted By:

sijina-test

Ray No. : RU/603

Signature:

Life Saving Rules: Tick on the boxes which you being discuss during TBT	
Don't walk under a suspended load	☑
Don't smoke outside designed smoking areas	☑
Conduct gas test when required	☐
Work with a valid work permit when required	☑
No drugs or alcohol while working or driving	☑
While driving don't use the mobile phone and exceed speed limit	☐
Obtain permit for working in confined Space	☑
Verify isolation before work begins and use the specified life protection	☑
Wear your seat belt	☑
Obtain authorization before overriding	☐
Follow prescribed journey	☑
Protect yourself against a fall when working at height	☑

Use hazards warning signs as remainders and tick the signs being discussed during TBT

☑	☑	☑	☑	☑	☑	☑	☑	☑

ATTENDANCE SHEET

S.No	Emp.No.	Name	Company	Designation	Signature
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115
	2,552	nim	Company1	h	sign_tbt_attendance_115