



RAY International Electrical Contracting & Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

INCIDENT NOTIFICATION

To be reported within 24 hours (maximum)

Abudhabi/ Dubai

DISTRIBUTION TO:

MD, CEO, GMs, Discipline SR MGR, QHSE MGR & advisors, LINE Managers, HRA Manager

REPORT ORIGINATED BY:

NAME:	Ramanuja	COMPANY / DIVISION:	RU/1048/22/PRJ	GSM NO:	050 1093229
--------------	----------	----------------------------	----------------	----------------	-------------

LOCATION OF INCIDENT:	CANLGRDN-MRKD(TOWE	DATE OF INCIDENT:	21-06-2023	TIME:	11:30 AM
------------------------------	--------------------	--------------------------	------------	--------------	----------

INCIDENT TYPE: Traffic Accident

INCIDENT ACTUAL SEVERITY RATING: 2
POTENTIAL SEVERITY RATING: 2
RISK LEVEL: Moderate

Note:
 Use the Risk Assessment Matrix to determine the **actual** and **potential** severity rating for the incident. Seek assistance from the HSE Advisor if required.

Incidents with a potential 'Medium or High Risk' shall be referred to the RAY QHSE Dept immediately

Low
Moderate
High

Likelihood \ Severity	Rare (1)	Unlikely (2)	Possible (3)	Likely (4)	Almost Certain (5)
Catastrophic (5)	Low	Moderate	High	High	High
Major (4)	Low	Moderate	Moderate	High	High
Moderate (3)	Low	Moderate	Moderate	Moderate	High
Minor (2)	Low	Moderate	Moderate	Moderate	Moderate
Negligible (1)	Low	Low	Low	Low	Low

BRIEF DESCRIPTION OF INCIDENT

on 21.06.2023, 11:30 hrs, During reversing the 3ton canter hi-up vehicle driver (Mr.Binder) didn't noticed the behind parked vehicle and he he hit parked 1ton pickup vehicle (D-84303, Leaseplan) and minor damages and scratches were happened to the 1ton pickup but nothing happened to 3ton canter hiup pickup(Y-65761).

BRIEF DESCRIPTION OF DAMAGE

found front bumper damaged

NUMBER OF PERSONS INJURED: 0

NAMES OF INJURED PEOPLE AND DETAILS OF INJURIES: N/A

THE FOLLOWING FOR LOW POTENTIAL INCIDENTS-

(All incidents including Medium or High Potential **MUST** have a full investigation report completed)

IMMEDIATE CAUSES 1.failure to check mirrors and blind spots.

UNDERLYING CAUSES due to negligence and lack of awareness.

CORRECTIVE AND PREVENTIVE ACTIONS:	RESPONSIBLE:	CLOSED DATE:
informed to the concerned management and obtained Dubai police report	Ramanuja Yakkaladevu	22.06.2023
1.Before reversing the vehicle driver/operator should check the blind spots. 2. flaxman should available while reversing the vehicle.	Ramkumar Venkatajalapathy	23.06.2023