



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 20-11-2024

Time: 05:54 PM

Location: jubi h

Client: client-249

Project Name: Project-249

Project No: Project-249


v = OK

N/A = Not Applicable

D = Defect

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
20-11-2024	20-11-2024	g	2 Kg	DCP	N/A	✓	D	hgg

Comments: g

Inspector				Site In charge			
Name:	sijinauser			Name:	Employee-2		
Designation:				Designation:			
Signature/Date:		20-11-2024	RAY No: Emp-2539	Signature/Date:			RAY No: Emp-2

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place