



RAY International Electrical Equipments Maintenance LLC

RAY International Electrical Contracting LLC

RAY International Power LLC

FIRE EXTINGUISHER INSPECTION LOG

Abu Dhabi/ Dubai

Date: 06-02-2025 Time: 11:54 AM Location: mtnr Client: THEJU

Project Name: LACHU Project No: 12345678

v = OK N/A = Not Applicable D = Defect

Date of Inspection	Due date of Inspection	Extinguisher Tag No.	Volume of the Cylinder	Contents	Pressure Gauge	Hoses	Safety Pin	Remarks / Signature
06-02-2025	06-02-2025	1	3 Kg	CO2	✓	N/A	N/A	hjhj

Comments: nj

Inspector				Site In charge			
Name:	VINI11			Name:	Employee-8		
Designation:				Designation:			
Signature/Date:	06-02-2025	RAY No:	Emp-40	Signature/Date:		RAY No:	Emp-8

Condition / fault to be checked:

Cylinder: - Free from damage, Label clean and legible, Owner clearly identified

Pressure Gauges: - Pressure reading within green section, Gauge clean and legible, Gauge free from damage

Contents: - Weight within specification, Cylinder inverted and bumped to loosen contents (for dry chemical only)

Hoses: - Free of obstruction, End cap in position, Connection checked for tightness, Free of cracks and deterioration

Safety Pin: - Secured from accidental displacement, Seal in place