

RAY International Electrical Contracting & Maintenance LLC RAY International Power LLC

| | | AT Intern | ational Power Li | LU | | | |
|---------------------------|---|--------------------|------------------------------|--------------|------------------|----------|---------------|
| L | IFTING GEAR | S INSPECT | ION CHECKLIST | | | Abu Dl | nabi/ Dubai |
| Date : 30- | 07-2024 | Location: | knr | | Clie | nt: A | ADC |
| Project Code: | RU/021/22/PRJ | | Project Details: | RU/021/22 | <u>I</u> /PRJ | | |
| SI. No Of LiftingGear: | 2 | | Detail Of df LiftingGear: | | | | |
| | | 17 | EMS | СОМІ | PLIAN | CE | |
| SI. No | | | | YES | NO | NA | REMARKS |
| | | | uipment | | | | |
| 1 | Does all lifting ta inspection? | ckles covered l | by valid third party | | | ✓ | |
| 2 | Lifting Gear Curr | ent Colour cod | e? | | | ✓ | |
| 3 | Is the SWL displa | ayed? | | | | ✓ | |
| 4 | Does all the liftin | g gears stored | properly? | | | √ | |
| 5 | In case of nylon/ sharp edges exis | | es protection from | | | ✓ | |
| 6 | Are hook & safet | y latch & wire r | ope in good condition? | | | √ | |
| 7 | Are all lifting tack | des in good co | ndition? | | | √ | |
| | | Pe | rsonnel | | | | |
| 8 | Is the In-charge of storing of lifting of | | aware about the | ✓ | | | |
| 9 | Does the In-char gears for any phy | | e inspecting of lifting | ~ | | | |
| 10 | Are all personne trained? | l involved in lift | ng appropriately | ✓ | | | |
| Comments | : qwerty | | | | | | |
| Inspected B | y: User1 | | | Site In char | ge: | Vijil | srael Johnson |
| Sign/Date: | | | | | | | |
| RAY No: | | | | RAY No: | | | |
| | DI 1/023 | | | 1 | | ום | 1/023 |

Signature:

| Ref No: FR-608 Version. No 01 Issued Date : 08.09.2016 Page No: 1 |
|---|
|---|