

RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

MOBILE CRANE CHECKLI	Abu Dhabi/ Dubai				
Date: 24-02-2024 Location: dlh		Client:			
Project Code: 004	Project Details: tr65trt8ui				
Site In charge: sijina-test	Registration	No.: s			
Make & Model: n	Driving licen Expiry:	se 13-01-2024			
Operator Name: a	Other Info:	Test Info			

SI. No ITEMS	СО	MPLIAN	ICE	REMARKS	ACTION TO BE TAKEN		
	YES	NO	NA				
1	Is the crane safe working load suitable for the job? (The total load should not exceed more than 60% of crane capacity)	√					
2	Is crane third party certificate available?	~					
3	Is operator third party certificate available?		✓				
4	Engine oil level	√					
5	Engine coolant level	√					
6	Hydraulic system oil level	√					
7	Seat Belts	√					
8	Condition of Battery and Lamps	√					
9	Condition of wind screen & windows	√					
10	Revolving lights in working condition.	√					
11	Guards of moving and rotating parts	✓					

Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	1	
---------	--------	-------------	----	-------------	------------	----------	---	--

			COMPLIANCE			IARKS	ACTION TO BE TAKEN		
SI. No	ITEMS	YES	NO	NA	IXEIV	IAITIO	AOTION TO	JE IAKEN	
	Horn	✓							
12									
12									
	Reverse Alarm								
40	1.0000000000000000000000000000000000000	✓							
13									
	Air conditioner								
	All conditioner	✓							
14									
	Tyre pressure & Tyre condition	✓							
15									
	Hook and Hook Latch	√			·				
16									
	Over-Hoist, Boom Limit	1							
17	Switches working		✓						
17									
	Over load trip.								
	Over load trip.		✓						
18									
	Boom Angle indicator	✓							
19									
	Safe Working Load indicator	✓							
20									
	Boom Brake & Lock	✓							
21		'							
	Main clutch		,						
20			✓						
22									
	Deterioration or leakage in								
	lines, tanks, hoses, valves,	✓							
23	pumps, cylinders and other								
	parts of air or hydraulic system								
	Fire Extinguisher in operator	✓							
24	cabin								
	Load chart provided	√							
25		1							
	Operator manual in crane								
26			✓						
20									
	Lattice boom lowered to	1	 						
	ground and fully inspected	✓							
27	, ,								
	Condition of the clines	 							
	Condition of the slings	✓							
28									
Ref No:	FR-604 Version. No)1	Issued	Date	08.09.2016	Dogo No:	2	
INCI NO.	version. No		′'	เออนซน	Date	00.00.2010	Page No:		

SI. No ITEMS	COMPLIANCE			REMARKS	ACTION TO BE TAKEN	
	YES	NO	NA			
29	Soil Condition	✓				
30	Safe distance from edge of excavation		√			
31	Out riggers fully extended	✓				
32	Outrigger pads in good condition	✓				
33	Stability of crane	✓				
34	Wheel chokes available	✓				
35	Anemometer in working condition.	✓				
36	Overhead And Below Ground, Minimum Limit Approach Regulation At All Times	√				
37	Safe Distance From Respective Equipment And Lines	√				
eneral Co	gene mments :	1	I		1	1
nspected	By: Sijina			Site	I/C : sijina-test	

Inspected By :	Sijina	Site I/C :	sijina-test
Sign/Date :	Freezo		
RAY No :	RU/603	RAY No :	RU/603

Signature:

Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	3	
---------	--------	-------------	----	-------------	------------	----------	---	--