

RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

MOBILE CRANE CHECKLIST	Abu Dhabi/ Dubai		
Date: 31-07-2024 Location: Knr	Client: AADC		
Project Code: RU/021/22/PRJ Project	t Details: RU/021/22/PRJ		
Site In charge: Vijil Israel Johnson	Registration No.: 12345		
Make & Model: md1	Driving license 04-08-2024 Expiry:		
Operator Name: op1	Other Info: Test Info		

01 N		COMPLIANCE			REMARKS	ACTION TO BE TAKEN		
SI. No	ITEMS	YES	NO	NA	_			
1	Is the crane safe working load suitable for the job? (The total load should not exceed more than 60% of crane capacity)			✓				
2	Is crane third party certificate available?			√				
3	Is operator third party certificate available?			√				
4	Engine oil level			√				
5	Engine coolant level			√				
6	Hydraulic system oil level			√				
7	Seat Belts			√				
8	Condition of Battery and Lamps			√				
9	Condition of wind screen & windows			√				
10	Revolving lights in working condition.			√				
11	Guards of moving and rotating parts			√				

Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	1	
---------	--------	-------------	----	-------------	------------	----------	---	--

		СО	MPLIAN	CE	REMARKS	ACTION TO I	BE TAKEN
SI. No	ITEMS	YES	NO	NA			
	Horn			√			
12							
	Reverse Alarm			✓			
13							
	Air conditioner						
	All conditioner			✓			
14							
	Tyre pressure & Tyre condition						
15				✓			
10							
	Hook and Hook Latch			√			
16							
	Over-Hoist, Boom Limit			✓			
17	Switches working						
	Over load trip.			✓			
18							
	Boom Angle indicator						
40	Boom Angle maleator			✓			
19							
	Safe Working Load indicator						
20	-			✓			
20							
	Boom Brake & Lock			√	· · · · · · · · · · · · · · · · · · ·		
21							
	Main clutch			✓			
22							
	Deterioration or leakage in						
	lines, tanks, hoses, valves,			✓			
23	pumps, cylinders and other						
	parts of air or hydraulic system Fire Extinguisher in operator					1	
0.4	cabin			✓			
24							
	Third party certificates of			√		1	
25	operator and equipment						
	Load chart provided			✓			
26							
	Operator manual in crane			✓			
27							
	Lattice boom lowered to					1	
	ground and fully inspected			✓			
28							
	<u> </u>	1	l 	<u> </u>		1	
Ref No:	FR-604 Version. No	10)1	Issued [Date 08.09.2016	Page No:	2

SI. No ITEMS	COMPLIANCE		CE	REMARKS	ACTION TO BE TAKEN		
	YES	NO	NA				
	Condition of the slings			√			
29							
	Soil Condition			√			
30							
	Safe distance from edge of			√			
31	excavation						
	Out riggers fully extended			√			
32							
	Outrigger pads in good			√			
33	condition						
	Stability of crane			√			
34				'			
	Wheel chokes available			✓			
35				'			
	Anemometer in working			√	·		
36	condition.			`			
00							
	Overhead And Below Ground,			√			
37	Minimum Limit Approach			*			
0.	Regulation At All Times						
	Safe Distance From			√			
38	Respective Equipment And			*			
30	Lines						
0	cm		<u> </u>	<u>I</u>	ı		
General Co	omments :						
Inspected	Inspected By: User1		Site	I/C: Vijil Israel Joh	nson		
Sign/Data							
Sign/Date	•						
DAY ::	DILLOGO				AN DUVOCO		
RAY No:	RU/023			RAY	' No : RU/023		

Signature:

Ref No: FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	3	
----------------	-------------	----	-------------	------------	----------	---	--