

RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

MOBILE CRANE CHECKLIST	Abu Dhabi/ Dubai						
Date : 12-11-2024 Location : kk	Client: client-187						
Project Code: Project-187 Project Details: Project-187							
Site In charge: Employee-2	Registration No.: nnn						
	riving license 13-11-2024 xpiry:						
Operator Name: nnn C	Other Info: Test Info						

SI. No	T	COMPLIANCE			REMARKS	ACTION TO BE TAKEN		
	ITEMS	YES	NO	NA				
1	Is the crane safe working load suitable for the job? (The total load should not exceed more than 60% of crane capacity)	√						
2	Is crane third party certificate available?	~						
3	Is operator third party certificate available?	√						
4	Engine oil level	√						
5	Engine coolant level	√						
6	Hydraulic system oil level	√						
7	Seat Belts	√						
8	Condition of Battery and Lamps	√						
9	Condition of wind screen & windows	√						
10	Revolving lights in working condition.	√						
11	Guards of moving and rotating parts	~						

Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	1
---------	--------	-------------	----	-------------	------------	----------	---

		COMPLIANCE			REMARKS		ACTION TO BE TAKEN		
SI. No	ITEMS	YES	NO	NA NA	'`	LINANIO	AOTION TO I	JE IAKEN	
	Horn	✓							
12		*							
12									
	Reverse Alarm	1							
40	1.676.667	✓							
13									
	Air conditioner		-						
	All conditioner	✓							
14									
	Tyre pressure & Tyre condition	✓							
15									
	Hook and Hook Latch	√							
16		*							
	Over-Hoist, Boom Limit								
4-7	Switches working	✓							
17									
	Over load trip.								
	Over load trip.	✓							
18									
	Boom Angle indicator	✓							
19									
	Safe Working Load indicator	√							
20									
	Boom Brake & Lock					•			
21		✓							
21									
	Main clutch								
	Wall Gaton	✓							
22									
	Deterioration or leakage in lines, tanks, hoses, valves,	✓							
23	pumps, cylinders and other								
	parts of air or hydraulic system								
	Fire Extinguisher in operator	√				•			
24	cabin	*							
-									
	Third party certificates of		1						
25	operator and equipment	✓							
25									
	Load chart provided		-						
	Load Graft provided	✓							
26									
			1			·			
	Operator manual in crane	✓							
27									
				<u> </u>	<u> </u>				
	Lattice boom lowered to	√							
28	ground and fully inspected								
I		1	<u> </u>	I	l 		l		
Ref No:	FR-604 Version. No		01	Issued	Date	08.09.2016	Page No:	2	
	l l								

SI. No	ITEMO	COMPLIANCE			REMARKS	ACTION TO BE TAKEN		
	ITEMS	YES	NO	NA				
	Condition of the slings	✓						
29								
	Soil Condition	✓						
30								
00								
	Safe distance from edge of							
0.4	excavation	✓						
31								
	Out riggers fully extended							
	Out riggers fully exterided	✓						
32								
	Outriessands							
	Outrigger pads in good condition	✓						
33	Condition							
	Stability of crane	✓						
34								
	Wheel chokes available	✓						
35		,						
00								
	Anemometer in working							
36	condition.	✓						
30								
	Overhead And Below Ground,							
	Minimum Limit Approach	✓						
37	Regulation At All Times							
	Safe Distance From		ļ					
	Respective Equipment And	✓						
38	Lines							
eneral Co	nnnnn mments :							
	D A director			3	/O			
nspected	By: Admin			Site I	/C: Employee-2			
ign/Date								
.g., Date	•							
AV Na :	Emp 2			DAY	Na. Fmn ?			
AY No:	Emp-2			RAY	No: Emp-2			

COMPLIANCE

REMARKS

ACTION TO BE TAKEN

Signature:

Ref No: FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	3	
----------------	-------------	----	-------------	------------	----------	---	--