

## RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC

## **RAY International Power LLC**

MOBILE CRANE CHECKLIS	Abu Dhabi/ Dubai					
Date: 01-07-2023 Location: gu		Client: tester				
Project Code: Procurement	oject Code: Procurement Project Details: gh					
Site In charge:     Gurushankar Thiyakarajan     Registration No.:     vh						
Make & Model: v Driving license 02-07-2023   Expiry:						
Operator Name: g	Other Info:	Test Info				

		COMPLIANCE				REMARKS		ACTION TO BE TAKEN		
SI. No	ITEMS	YES NO NA								
37	Overhead And Below Ground, Minimum Limit Approach Regulation At All Times	~								
38	Safe Distance From Respective Equipment And Lines	~								
1	Is the crane safe working load suitable for the job? (The total load should not exceed more than 60% of crane capacity)	~								
2	Is crane third party certificate available?	~								
3	Is operator third party certificate available?	~								
4	Engine oil level	~								
9	Condition of wind screen & windows	~								
10	Revolving lights in working condition.	~								
15	Tyre pressure & Tyre condition	~								
16	Hook and Hook Latch	~								
5	Engine coolant level	~								
6	Hydraulic system oil level	~								
Ref No:	01 <b>Version. No</b>		01		Issued I	Date :	7/13/2023	Page No:	1	

MOBILE CRAI	NE CHECKLIST	Abu Dhabi/ Dubai		
Date: 01-07-2023 L	<b>_ocation:</b> gu	Client: tester		
Project Code: Procurement	Project Details:	h		
Site In charge: Gurushankar	Thiyakarajan Registratio	ו No.: vh		
Make & Model: v	Driving lice Expiry:	se 02-07-2023		
Operator Name: g	Other Info:	Test Info		

SI. No		COMPLIANCE			REMARKS		ACTION TO BE TAKEN		
JI. NU	ITEMS	YES	NO	NA					
7	Seat Belts	✓							
7									
	Condition of Battery and								
8	Lamps	✓							
	Lamps								
21	Boom Brake & Lock	~							
21		<b>v</b>							
22	Main clutch	✓							
	Guards of moving and rotating								
11	parts	~							
12	Horn	~							
	Reverse Alarm								
13		~							
14	Air conditioner	~							
	Operator manual in crane								
27		~							
28	Lattice boom lowered to	~							
	ground and fully inspected	1							
	Over-Hoist, Boom Limit				·				
17	Switches working	✓							
		1							
18	Over load trip.	~							
10									
	Boom Angle indicator	+			·				
19		✓							
		1							
		1							
	1	I	<u> </u>	1					
Ref No:	01 Version. No	C	)1	Issued I	Date :	7/13/2023	Page No:	2	

MOBIL	E CRANE CHECKLIST	Abu Dhabi/ Dubai
Date: 01-07-2023	Location: gu	Client: tester
Project Code: Procu	rement P	roject Details: gh
Site In charge: Guru	ushankar Thiyakarajan	Registration No.: vh
Make & Model: V		Driving license 02-07-2023 Expiry:
Operator Name: g		Other Info: Test Info

SI. No	ITEMO			PLIAN		REMARKS		ACTION TO B	BE TAKEN
51. NO	ITEMS	YES		NO	NA				
20	Safe Working Load indicator	~							
33	Outrigger pads in good condition	~					· · ·		
34	Stability of crane	~							
23	Deterioration or leakage in lines, tanks, hoses, valves, pumps, cylinders and other parts of air or hydraulic system	~							
24	Fire Extinguisher in operator cabin	~							
25	Third party certificates of operator and equipment	~							
26	Load chart provided	~							
35	Wheel chokes available	~							
36	Anemometer in working condition.	~							
29	Condition of the slings	~							
30	Soil Condition	~							
31	Safe distance from edge of excavation	~							
32	Out riggers fully extended	~					· ·		
Ref No:	01 Version. No	•	01		Issued I	Date :	7/13/2023	Page No:	3

MOBILE CRANE CHECKLIST							Abu Dhabi/ Dubai		
Date: 01-07-2023 Location: gu						•	Client: tester		
Project Code: Procurement Project Details: gh						gh			
Site In charge:	Gurushank	ar Thiyakarajan			Registrati	on No.	: vh		
Make & Model:	Make & Model: v Driving license 02-07-2023   Expiry: Expiry:								
Operator Name:	g				Other Info	Те	st Info		
SI. No	ITE	MS	CC YES			REMARKS ACTION TO BE TAK			
General Comments :									
Inspected By : treesaSang					Site	Site I/C : Gurushankar Thiyakarajan			
Sign/Date :					Sig	n/Date	:		
RAY No :	23-07-0000	)2			RA	( No :	23-07-00002		