



RAY International Electrical Contracting & Maintenance LLC
RAY International Electrical Contracting LLC
RAY International Power LLC

MOBILE CRANE CHECKLIST

Abu Dhabi/ Dubai

Date: 07-08-2023

Location: knr

Client: client 1

Project Code: SangProject1

Project Details: sang project

Site In charge: sijina-test

Registration No.: a

Make & Model: h

Driving license 11-08-2023
Expiry:

Operator Name: a

Other Info: Test Info

Sl. No	ITEMS	COMPLIANCE			REMARKS	ACTION TO BE TAKEN
		YES	NO	NA		
36	Overhead And Below Ground, Minimum Limit Approach Regulation At All Times	✓				
37	Safe Distance From Respective Equipment And Lines		✓			
1	Is the crane safe working load suitable for the job? (The total load should not exceed more than 60% of crane capacity)	✓				
2	Is crane third party certificate available?	✓				
3	Is operator third party certificate available?		✓			
4	Engine oil level	✓				
10	Revolving lights in working condition.	✓				
16	Hook and Hook Latch		✓			
5	Engine coolant level	✓				
6	Hydraulic system oil level		✓			
7	Seat Belts	✓				

Ref No: FR-604

Version. No

01

Issued Date

08.09.2016


Page No:

1

SI. No	ITEMS	COMPLIANCE			REMARKS	ACTION TO BE TAKEN	
		YES	NO	NA			
8	Condition of Battery and Lamps	✓					
9	Condition of wind screen & windows	✓					
22	Main clutch	✓					
11	Guards of moving and rotating parts	✓					
12	Horn		✓				
13	Reverse Alarm		✓				
14	Air conditioner		✓				
15	Tyre pressure & Tyre condition	✓					
28	Condition of the slings	✓					
17	Over-Hoist, Boom Limit Switches working	✓					
18	Over load trip.		✓				
19	Boom Angle indicator	✓					
20	Safe Working Load indicator		✓				
21	Boom Brake & Lock		✓				
34	Wheel chokes available		✓				
23	Deterioration or leakage in lines, tanks, hoses, valves, pumps, cylinders and other parts of air or hydraulic system	✓					
24	Fire Extinguisher in operator cabin	✓					
Ref No:	FR-604	Version. No	01	Issued Date	08.09.2016	Page No:	2

SI. No	ITEMS	COMPLIANCE			REMARKS	ACTION TO BE TAKEN
		YES	NO	NA		
25	Load chart provided	✓				
26	Operator manual in crane	✓				
27	Lattice boom lowered to ground and fully inspected	✓				
35	Anemometer in working condition.		✓			
29	Soil Condition	✓				
30	Safe distance from edge of excavation	✓				
31	Out riggers fully extended	✓				
32	Outrigger pads in good condition	✓				
33	Stability of crane	✓				

General Comments :
fgujnn
hghhhhjjjjhh
bhjjfgujnn
hghhhhjjjjhh
bhjj
fgujnn
hghhhhjjjjhh
bhjj
fgujnn
hghhhhjjjjhh
bhjj
fgujnn
hghhhhjjjjhh
bhjj

Inspected By : Sijina	Site I/C : sijina-test
Sign/Date : 	
RAY No : RU/603	RAY No : RU/603

Signature: