

## RAY International Electrical Contracting & Maintenance LLC RAY International Electrical Contracting LLC RAY International Power LLC

QHS	SE SITE INS	SPECTION CH	Abu Dhabi/ Dubai					
<b>Date</b> : 20-06-20	20-06-2023 <b>Location</b> :				Cli	Client: abu dhabi		
Project Code: ABU DHABI-COM-RES S		RESOURCE	Project Details:	ABU DH	IABI-C	OM-RESOURCES		
Activity			Site Incharge:	Hind Yaicl	h Acho	pur		

CI Na	Task Description			COMP	LIANCE		DEMARKO			
SI. No					YES	NO	NA	REMARKS		
		HSE								
	Check that PT\	N/ NOC's available at s	site.							
12					<b>✓</b>					
	Check if any In	ternal Permits issued a	nd validit	.V						
13	ensured.	•		✓						
	Ensure that ele	ectrical safety rules and	procedu	re are						
14	followed.			<b>√</b>						
	Check the avai	lability of Job HSE plar	n and Risl	k		<b>√</b>				
15	Assessment M	atrix for the activity.				<b>,</b>				
	Check that the	toolbox talk is conducte	ed before	starting	<b>✓</b>					
16	the activity and	recorded.			*					
		ork is being carried out	on the co	rrect	<b>√</b>					
17	piece of Equipr	ment/OHL.								
	Check the cond	dition of tools & tackles				<b>√</b>				
18						Ť				
		de in Power tools, liftin	g tools ar	nd		<b>√</b>				
19	tackles.									
		lability of first aid boxes	s with che	ecklist	<b>√</b>					
20	duly filled and s	signea.								
04	Check the avai	lability of First aider an	d Fire wa	rden.	<b>✓</b>					
21										
22		dition of Fire extinguish ty of monthly inspectior		ated and		✓				
22										
Check good le		vel of Housekeeping ma	aintained	at site.			✓			
24	Waste dispose	d from site appropriatel	ly.				✓			
24										
25	Check the stora	age of material appropr	riate at sit	ie.			✓			
	Chook all wards	force in site with	oriota DD	Fand						
26	using it.	force is site with approp	priate PPI	⊏ and		✓				
	Check in rando	lition								
27	clean and hygic		✓							
-			ing 3rd no	artv						
28	Check the machinery/ equipment having 3rd party certificate and operator certified.					✓				
		ear Miss report records	availahla							
29	J STOT Card, Ne	ai miss report recolus	avallable			✓				
			<u> </u>		<u>                                     </u>					
Ref No: FR-426		Version. No	04	Issued	Date :	20.	06.2023	Page No:	1	

SI. No				PLIANCE		REMARKS	
31. NO		•	YES	NO	NA	REWARKS	
30		abour welfare facilities are at site like umbrella/ king water facilities etc. are available.			✓		
31	Check su RAY Logo	fficient barricading facilities are available with o in it.		✓			
32	Check too placed at	ols mat is available at site and all tools are tool mat.		<b>✓</b>			
33		andatory sign boards like project sign board, ork, unauthorized entry, etc. are displayed at			<b>√</b>		
34		ifficient lighting arrangement and warning available at site.		✓			
35	dfeawed			<b>✓</b>			
1	tester ed	lit	<b>√</b>				
		Quality		•		·	
1	Check the statemen	e availability of controlled copy of method t.	<b>✓</b>				
2		nether the team is aware of the work logy and Risk assessment.	<b>√</b>				
3		at measuring/ Testing equipment have valid n certificate & calibration sticker.	<b>~</b>				
4		at sufficient tools and materials are available out the job.	<b>✓</b>				
5	Check the out the jo	at proper tools and materials are used to carry b.	<b>√</b>				
6	Check whactivity.	nether proper planning has been done for the	<b>√</b>				
7	Check the	at sufficient manpower available to carry out ty.	<b>√</b>				
8	Check whether plan for Tomorrow/Next week/ Next month available						
9	Check whether mandatory site documents are available at site.						
10	Check vehicle log sheet is entered properly and signed by supervisors.						
11	oour timecard is filled on daily basis with or signature.	✓					
Comments	et						
Inspected By(RAY)					Rev	viewed By (RAY)	
Name 123trees		123treesaSang		K.Rajkumar			
Designation	1	TestDesgntion		TestDesgntion			
Signature&l	Date						

Ref No:	FR-426	Version. No	04	Issued Date :	20.06.2023	Page No:	2
---------	--------	-------------	----	---------------	------------	----------	---